

On-Hand available sensors

| Sensor type | Full Scale | Qty |
|----------------------|------------|-----|
| Accelerometers | +/-10g | 81 |
| String potentiometer | +/-1" | 1 |
| String potentiometer | +/-2.5" | 32 |
| String potentiometer | +/-5" | 6 |
| String potentiometer | +/-6" | 8 |
| String potentiometer | +/-10" | 20 |
| String potentiometer | +/-12.5" | 21 |
| String potentiometer | +/-15" | 11 |
| String potentiometer | +/-25" | 25 |
| String potentiometer | +/-60" | 7 |
| Linear potentiometer | +/-1" | 59 |
| Linear potentiometer | +/-2" | 18 |
| Linear potentiometer | +/-4" | 40 |
| | | |