

On-Hand Available Sensors

Sensor type	Full Scale	Qty
Accelerometers	+/- 5g	15
Accelerometers	+/- 10g	195
String potentiometer	+/- 1"	1
String potentiometer	+/- 2.5"	28
String potentiometer	+/- 5"	18
String potentiometer	+/- 10"	27
String potentiometer	+/- 15"	26
String potentiometer	+/- 25"	9
String potentiometer	+/- 30"	10
Linear potentiometer	+/- 1"	65
Linear potentiometer	+/- 2"	28
Linear potentiometer	+/- 3"	17
Linear potentiometer	+/- 4"	32